





OFFSET CLEAT (OFFC1)



GUTTER @ LOWER EAVE (GTR1)



GUTTER STRAPS (GTR1/ST)



***NOTE: SLIDING SNOW AND ICE COULD CAUSE DAMAGE TO GUTTER SYSTEM.**



GUTTER @ LOWER EAVE

2529 WEST JACKSON ST, PHX, AZ 85009
PH: (602) 275-1676 FAX: (602) 275-1739

PANEL SYSTEM: NS-10	
ISSUE / REVISION DATE: 1/11/2013	DETAIL NO. NS10-GTR1
NOT TO SCALE	