



***NOTE: SLIDING SNOW AND ICE COULD CAUSE DAMAGE TO GUTTER SYSTEM.**



GUTTER W/ DRIP @ LOWER EAVE

2529 WEST JACKSON ST, PHX, AZ 85009
 PH: (602) 275-1676 FAX: (602) 275-1739

PANEL SYSTEM: SL-175	
ISSUE / REVISION DATE: 1/11/2013	DETAIL NO. SL175-GTR/D
NOT TO SCALE	